

AD-A070 697

BERGER ASSOCIATES INC HARRISBURG PA

F/G 13/2

NATIONAL DAM INSPECTION PROGRAM. SPEEDWELL FORGE DAM (NDS-PA-00--ETC(U)


DACW31-79-C-0012

NI


UNCLASSIFIED

| OF |

AD-A
070697



END
DATE
FILMED
8-79
DDC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

LEVEL



WDA 0020 R 0.4

SUSQUEHANNA RIVER BASIN

SPEEDWELL FORGE DAM


NDS No. PA-00345

DER No. 36-257

LANCASTER COUNTY, PENNSYLVANIA

PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM

Distribution Unlimited
Approved for Public Release
Contract No. DACW31-79-C-0012



PREPARED FOR
DEPARTMENT OF THE ARMY
Baltimore District, Corps of Engineers
Baltimore, Maryland 21203

BY

Berger Associates, Inc.
Harrisburg, Pennsylvania

FEBRUARY 1979

DDC FILE COPY

THIS DOCUMENT IS BEST QUALITY PRACTICABLE.
THE COPY FURNISHED TO DDC CONTAINED A
SIGNIFICANT NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.

41103 79 06 28 054

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DDC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

PREFACE

This report has been prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

6 National Dam Inspection Program.
Speedwell Forge Dam (NDS-PA-00345,
DER-36-257), Susquehanna River Basin,
Lancaster County, Pennsylvania. Phase
I Inspection Report.

11 Feb 79 12 76p.

15 DACW 31-79-C-0012¹

411 003

| | | | | | | | | |
|---------------|-------------------------------------|--------------------------|--------------------------|---------------|----|--------------|-------------------|----------------------|
| ACCESSION FOR | WIS G.A.I. | DEC TAB | Unannounced | Justification | By | Distribution | Availability Code | Available/or special |
| | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | | | | 23012 |
| | | | | | | | | A |

JCR

PHASE I REPORT

NATIONAL DAM INSPECTION PROGRAM

BRIEF ASSESSMENT OF GENERAL CONDITIONS
AND RECOMMENDATIONS

[CONT'D FROM
P. 1]

Name of Dam: SPEEDWELL FORGE DAM, NDS NO. PA-00345
State & State No. PENNSYLVANIA, 36-257
County: LANCASTER
Stream: HAMMER CREEK
Date of Inspection: October 30, 1978

Based on the visual inspection, past performance and the available engineering data, the dam and its appurtenant structures appear to be in good condition.

The hydrologic and hydraulic calculations indicate that the spillway for this dam has the capacity for passing 47 percent of the Probable Maximum Flood (PMF) without overtopping the embankment. Although 1/2 PMF will cause some overtopping, the depth of flow due to the overtopping is less than that judged to cause failure and therefore, the spillway, while inadequate, is not considered seriously inadequate.

The following recommendations are made for action by the owner:

1. That the low areas in the dam breast be raised to the original design height.
2. That heavy riprap be placed at the end of the right stilling basin slab.
3. That a formal surveillance and downstream warning system be developed to be used during periods of high or prolonged precipitation.

SUBMITTED BY:

BERGER ASSOCIATES, INC.
HARRISBURG, PENNSYLVANIA

DATE: February 20, 1979



APPROVED BY:

[Signature]

G. K. WITHERS
Colonel, Corps of Engineers
District Engineer

DATE 21 Mar 79



OVERVIEW
SPEEDWELL FORGE DAM

TABLE OF CONTENTS

| | <u>Page</u> |
|--|-------------|
| SECTION 1 - <u>PROJECT INFORMATION</u> | |
| 1.1 GENERAL | 1 |
| 1.2 DESCRIPTION OF PROJECT | 1 |
| 1.3 PERTINENT DATA | 2 |
| SECTION 2 - <u>ENGINEERING DATA</u> | |
| 2.1 DESIGN | 6 |
| 2.2 CONSTRUCTION | 6 |
| 2.3 OPERATION | 7 |
| 2.4 EVALUATION | 7 |
| SECTION 3 - <u>VISUAL INSPECTION</u> | |
| 3.1 FINDINGS | 8 |
| 3.2 EVALUATION | 9 |
| SECTION 4 - <u>OPERATIONAL PROCEDURES</u> | |
| 4.1 PROCEDURES | 10 |
| 4.2 MAINTENANCE OF DAM | 10 |
| 4.3 MAINTENANCE OF OPERATING FACILITIES | 10 |
| 4.4 WARNING SYSTEM | 10 |
| 4.5 EVALUATION | 10 |
| SECTION 5 - <u>HYDROLOGY/HYDRAULICS</u> | |
| 5.1 EVALUATION OF FEATURES | 11 |
| SECTION 6 - <u>STRUCTURAL STABILITY</u> | |
| 6.1 EVALUATION OF STRUCTURAL STABILITY | 13 |
| SECTION 7 - <u>ASSESSMENT AND RECOMMENDATIONS</u> | |
| 7.1 DAM ASSESSMENT | 15 |
| 7.2 RECOMMENDATIONS | 15 |
| APPENDIX A - CHECK LIST OF VISUAL INSPECTION REPORT | |
| APPENDIX B - CHECK LIST OF ENGINEERING DATA | |
| APPENDIX C - HYDROLOGY AND HYDRAULIC CALCULATIONS | |
| APPENDIX D - GEOLOGIC REPORT | |
| APPENDIX E - PHOTOGRAPHS | |
| APPENDIX F - PLATES | |

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

SPEEDWELL FORGE DAM

NDS-ID NO. PA-00345

DER-ID NO. 36-257

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

A. Authority

The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspections of dams throughout the United States.

B. Purpose

The purpose is to determine if the dam constitutes a hazard to human life and property.

1.2 DESCRIPTION OF PROJECT

A. Description of Dam and Appurtenances

Note: Elevations in this report are based upon the datum provided on the designers construction drawings with the top of dam elevation at 125.0 which is approximately equal to M.S.L. Elevation 405.0 on the U.S.G.S. map. Therefore, all design elevations have been increased by 280 feet.

Speedwell Forge Dam, formerly known as Hammer Creek Dam, is a zoned earthfill dam with a maximum height of 35 feet above the streambed. The embankment length is 830 feet and the top of dam has a width of 18 feet. A cutoff trench was excavated along the centerline of the dam to the top of solid rock. A 120 foot long trapezoidal spillway weir is located in the right abutment at an elevation of 10 feet below the top of the dam. The concrete spillway ends in a stilling basin, from which the water flows through a riprap lined discharge channel to the original creekbed. A concrete control tower is located upstream just off the breast of the dam. Discharge through a 4-foot square concrete conduit is regulated either by stop logs or by opening a 30-inch sluice gate.

→ [CONT'D ON
P. ii]

- B. Location: Elizabeth Township, Lancaster County, PA
U.S.G.S. Quadrangle, Lititz, PA
Latitude 40°-12.2', Longitude 76°-18.5'
(Appendix F, Plates I and II)
- C. Size Classification: Intermediate (35 feet high,
2,299 acre-feet)
- D. Hazard Classification: High (Section 3.1.E)
- E. Ownership: Pennsylvania Fish Commission
P. O. Box 1673
Harrisburg, PA 17120
- F. Purpose of Dam: Recreation
- G. Design and Construction History

This dam was designed by Jordan, McNee, Parnum & Yule, Consulting Engineers, located in Philadelphia, Pennsylvania, for the Pennsylvania Fish Commission. The design and construction was accomplished under supervision of the General State Authority of Pennsylvania. Final construction plans were approved in 1964 and a permit for construction was issued on January 12, 1965.

The Contractor, Roger E. Gerhart from Lititz, Pennsylvania, started construction in April, 1965, and completed the work in January, 1966.

H. Normal Operating Procedures

The reservoir is used only for recreation, fishing and boating. The reservoir has been lowered several times for maintenance of docks and fish management.

1.3 PERTINENT DATA

A. Drainage Area (square miles)

Computed for this report 24.1
(original design used 24.95 sq.mi.)

B. Discharge at Dam Site (cubic feet per second) See Appendix C for hydraulic calculations.

Maximum known flood, June 22, 1972 (Agnes)
estimated on basis of pool Elev. 401.0 6,740

Warm water outlet None

| | |
|---|--------|
| Outlet works low-pool outlet at pool Elev. 376 | 50 |
| Outlet works at pool level Elev. 394.4 | 135 |
| Spillway capacity at pool Elev. 404.6 (low point) (top of dam) | 12,850 |
| Spillway capacity at pool Elev. 405 (Design - top of dam) | 13,660 |
| C. <u>Elevation</u> (feet above mean sea level) | |
| Top of dam (low point) | 404.6 |
| Top of dam, design elevation | 405.0 |
| Spillway crest | 395.0 |
| Upstream portal invert of outlet tunnel | 369.7 |
| Downstream portal invert of outlet tunnel | 369.0 |
| Streambed at centerline of dam | 370.0 |
| Maximum tailwater about (from Designer) | 384.0 |
| D. <u>Reservoir</u> (miles) | |
| Length of maximum pool | 2.5 |
| Length of normal pool | 1.5 |
| E. <u>Storage</u> (acre-feet) | |
| Spillway crest (Elev. 395) | 970 |
| Top of dam (Elev. 404.6) | 2,299 |
| Top of dam (Design Elev. 405) | 2,372 |
| F. <u>Reservoir Surface</u> (acres) | |
| Top of dam (Elev. 405) | 186 |
| Spillway crest (Elev. 395) | 106 |

G. Dam

See Plates III through VII, Appendix F, for plan and sections.

Type: Rolled earthfill.

Length: 830 feet embankment and 120 feet spillway.

Height: 35 feet above streambed.
45 feet above bottom cutoff trench.

Top Width: 18 feet.

Sideslopes: Upstream 2.5H to 1V
Downstream 2.5H to 1V.

Zoning: Impervious material in core. Less impervious material in upstream and downstream sections.

Impervious Core: Top width 18 feet with side slopes of 1.0H to 1.5V.

Cutoff: Trench on centerline dam excavated to rock and a bottom width of 20 feet, side slopes 1H to 1V. Trench filled with impervious material.

Grout Curtain: None.

H. Outlet Facilities

The outlet facility consists of a 4-foot square reinforced concrete conduit with an upstream headwall, wingwalls and trash rack from the upstream toe to a control tower located adjacent to the breast of the dam. The concrete tower, with inside dimensions of 4 feet 6 inches by 6 feet 5 inches, has a 30-inch square sluice gate for drawdown and 5 feet long stoplogs for normal pool level control. The concrete conduit, with a total length of 180 feet, ends at the downstream end in a riprapped channel. Provisions have been made to block off the discharge channel to form a fish catch basin.

I. Spillway

Type: Uncontrolled, concrete lined trapezoidal weir and channel at the right abutment.

Length of Weir: 120 feet.

Crest Elevation: 395.0

Upstream Channel: The forebay area has been excavated to an elevation of 3 feet below top of weir. The right embankment is excavated into the hillside and is protected with riprap. On the left side, a concrete retaining wall retains the embankment slope. The water approaching the spillway has to go through a considerable change of direction.

Downstream Channel: The spillway drops 2 feet below the weir and then descends on a 20 percent slope to a 4 feet deep stilling basin with a trapezoidal cross section. The width of the spillway narrows down to a 90 foot width. The stilling basin has a 30 foot long low flow notch. The channel beyond the stilling basin has a trapezoidal section and is protected with riprap.

J. Regulating Outlets

See Section 1.3.H.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

A. Hydrology and Hydraulics

The design for this dam was based on PennDER's C curve and a hydrologic analysis was not made. The files of the Pennsylvania Department of Environmental Resources (PennDER) did not contain hydrographs, storage area curves, nor discharge curves. The hydraulic computations available were limited to the design of the spillway length based on the C-curve and the maximum depth of tailwater with maximum discharge, calculated as 10.8 feet for 14,100 cfs.

B. Embankment

The embankment design was based on data obtained from test borings and auger borings drilled along the centerline of the dam and in the proposed borrow areas. A foundation report was prepared by the designer and is available in the files of PennDER. This report discusses the geology of the site, the results of field exploration, laboratory tests and soil classifications. The report also includes slope stability analyses for the maximum section for three cases; (1) end of construction, (2) steady seepage normal pool and (3) sudden drawdown. The factors of safety are shown as 2.79, 1.92 and 1.15 respectively. A downstream toe drain is included in the design over the full length of the embankment. The cutoff trench was to be excavated to the top of rock or two feet into rock if rock was fragmented.

C. Appurtenant Structures

The files of PennDER did not contain design criteria or design analysis for the appurtenant structures. The available data consists of the construction drawings and the foundation report.

2.2 CONSTRUCTION

Construction of these facilities was under daily supervision of a G.S.A. inspector and weekly inspection by the designer and PennDER. The trench was excavated to the top of rock and backfilled with a clayey material excavated for the spillway. Sand and gravel excavated from the spillway area was placed in the upstream zone and shaley material excavated from the forebay area was placed in the downstream area of the embankment. Regular compaction tests were made in the field, but only a few results were in the file. The results appear to be satisfactory. Construction photographs are in the file and indicate good workmanship.

During the excavation of the stilling basin, springs were exposed having a head of about 4 to 5 feet. The weight of the concrete slab and the water in the basin were considered sufficient to prevent uplift and no weep holes were installed to relieve pressure in the basin. The spillway chute was partially over excavated by about one foot and back-filled with gravel and sand.

Compaction of the embankment was accomplished with sheepsfoot rollers and a 17-ton Buffalo-Springfield compactor.

2.3 OPERATION

No formal records of operation have been maintained by the owner. The lake level has been lowered quite often (1971, 1972, 1975 and 1976) for fish management and repair or installation of boat docks.

2.4 EVALUATION

A. Availability

The engineering data available for review was in the files of PennDER. The design consultants did not have additional design data in their files. Drawings in the Office of the Fish Commission were limited to construction drawings and some shop drawings.

B. Adequacy

The available construction and engineering data is considered to be adequate to make a reasonable assessment of these facilities.

C. Operating Records

Formal records of operation are not maintained. The inspection reports of PennDER do not indicate that major problems have occurred at these facilities since construction was completed.

D. Post Construction Changes

No changes have been made to these facilities since construction was completed.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

A. General

The general appearance of the Speedwell Forge Dam was good. The relatively recently constructed dam has required little maintenance. No mowing of the seeded areas has been done. The visual inspection check list is contained in Appendix A of this report. Photographs made during the inspection are reproduced in Appendix E. The inspection was made in company of Mr. Jon Grindall, P.E., of the Bureau of Fisheries and Engineering, and Mr. Ray Stichler, Field Supervisor. At the time of inspection, the pool level was about 4 to 5 feet below the spillway weir for control of weed growth during the winter months.

B. Embankment

The upstream slope is riprapped to five feet above normal pool and is seeded above that level. The riprap was in good condition and no sloughage or erosion was noticed. The top of dam is covered with grass and weeds. The downstream slope has a good cover consisting of crown vetch, which however prevents a close inspection of the surface. No signs of distress were detected. Trucks, used for some maintenance work, have scarred the surface at a few places. These bare areas will be reseeded in the spring according to the owner's representative.

Two low areas were noticed during the inspection. Half the breast width of the dam has a low area adjacent to the left spillway wall, reducing the actual top of the dam to half of its intended surface width. The area immediately next to the right spillway wall is also low and the seepage key is exposed. The toe of the dam is dry and no seepage was detected. A survey of the profile of the dam (Appendix A, Plate A-I) indicates that the dam breast is lower than the design height over a length of about 700 feet. At a point near the left abutment the maximum difference of 0.4 feet lower than design elevation occurs.

C. Appurtenant Structures

The intake control structure is located adjacent to the breast of the dam. Steel rungs lead to a platform at elevation 397.0, which is two feet above spillway elevation. The tower was in good condition and the 30-inch x 30-inch sluice gate was partially opened during the inspection. Normal pool level variations are controlled with stoplogs. The outlet channel for the 4 feet square concrete conduit has heavy riprap and was in excellent condition.

The spillway, located in the right abutment, has an 8-inch wide trapezoidal concrete weir and did not show any deterioration except some shrinkage cracking. The approach was clear and well defined. The entrance training walls appear to be short and riprap was dislodged during the relatively high discharges with Agnes in 1972.

The concrete abutment walls and spillway chute lining and walls were in excellent condition, as was the stilling basin and the sloped paving on the side of the stilling basin. Some erosion occurred during Agnes at the end of the right slab. Concrete was pumped under the slab and riprap was placed at the end of the slab. Some additional heavy stone should be placed at the end of that slab.

D. Reservoir Area

The banks of the impounded lake are flat and stable. The immediate area adjacent to the lake is mostly wooded with some agriculture. No sedimentation has been reported.

E. Downstream Channel

The discharge channel below the stilling basin is wide and clear and unobstructed until it joins the original creekbed. About 1,000 feet downstream, 5 farm buildings and houses are located close to the floodplain before the creek crosses under a highway. It is expected that more than a few lives would be endangered if the dam would fail due to overtopping. The hazard category is considered to be "High".

3.2 EVALUATION

The visual inspection indicates that the dam is in good condition. Some minor maintenance work is required to fill the low areas adjacent to the spillway abutment walls.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURE

This lake was created for fishing and small boats. Fish management requires good weed control and the level of the lake is adjusted as required. The sluice gate and stoplogs are adjusted frequently (at least six times a year).

4.2 MAINTENANCE OF DAM

There is no regular procedure for dam maintenance. No mowing of the top is done and the crown vetch on the downstream slope requires little or no maintenance. The owner is aware that brush growth should be prevented.

4.3 MAINTENANCE OF OPERATING FACILITIES

The operating facilities are in good condition. The sluice gate operator stand is greased and small areas of erosion which occurred during Agnes have been repaired.

4.4 WARNING SYSTEM

The Fish Commission maintains a Regional Office near the lake and patrol officers visit the dam site on at least a daily basis. A copy of an emergency plan was shown to the inspectors. This plan lists the phone number of the Regional DER Office in Harrisburg and stipulates the conditions the patrolman has to watch for. It does not include a downstream warning plan.

4.5 EVALUATION

The maintenance procedures are satisfactory at the present. It is recommended that a formal surveillance and warning system be developed. A concern is the operator's stand at an elevation only two feet above the spillway. In case of an emergency this drawdown facility could not be used during high pool levels.

SECTION 5 - HYDROLOGY/HYDRAULICS

5.1 EVALUATION OF FEATURES

A. Design Data

The Hydrologic and Hydraulic Analyses available from PennDER for Speedwell Forge Dam were not very extensive. No stage-storage curve, stage discharge curve, flood hydrographs or flood routings were available. The spillway was designed to pass the C-curve flood of 14,100 cfs.

B. Experience Data

The maximum record flood event at this dam site occurred in 1972. During this event, the water surface was noted to be about 6 feet higher than the spillway crest. With the exception of some erosion in the approach channel and under the right spillway slab, this flood was passed without difficulty.

C. Visual Observations

On the date of the inspection, no conditions were observed that would indicate that the appurtenant structures of the dam could not operate satisfactorily during a flood event, until the dam is overtopped.

D. Overtopping Potential

Speedwell Forge Dam has a total storage capacity of 2,299 acre-feet at the elevation of the low point in the embankment and an overall height of 35 feet above streambed. These dimensions indicate a size classification of "Intermediate". The hazard classification is "High" (see Section 3.1.E).

The recommended Spillway Design Flood (SDF) for a dam having the above classifications is the Probable Maximum Flood (PMF). For this dam, the PMF peak inflow is 27,480 cfs (See Appendix C for HEC-1 inflow computations).

Comparison of the estimated PMF peak inflow of 27,480 cfs with the estimated existing spillway discharge capacity of 12,850 cfs indicates that a potential for overtopping of the Speedwell Forge Dam exists.

An estimate of the storage effect of the reservoir and routing of the computed inflow hydrograph through the reservoir shows that this dam does not have the necessary storage available to pass the PMF without

overtopping. The present spillway-reservoir system can pass a flood event equal to 47% of a PMF.

If the low area in the embankment would be raised to the design elevation of 405.0, the spillway-reservoir system would be able to pass a flood event equal to 51% of a PMF.

E. Spillway Adequacy

The intermediate size category and high hazard category, in accordance with the Corps of Engineers criteria and guidelines, indicates that the Spillway Design Flood (SDF) for this dam should be the full Probable Maximum Flood (PMF).

The calculations show that the spillway discharge capacity and reservoir storage capacity combine to handle 47% of the (PMF) without overtopping the dam (refer to Sheet 5, of Appendix C). These calculations have considered the existing low point along the embankment crest.

Being an earth embankment dam, it is judged that a breach is likely to develop when the depth of flow over the embankment crest is 0.5 foot or greater. These studies also indicate that the depth of flow over the crest of the embankment due to one-half PMF is less than 0.5 foot. On the basis of this information, it is judged that a one-half PMF will cause some overtopping of the embankment but not enough to cause a breach. Therefore, the spillway capacity is considered to be inadequate, but not seriously inadequate.

The hydrologic analysis for this investigation was based upon existing conditions of the watershed. The effects of future development were not considered.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

A. Visual Observation

1. Embankment

There were no visual indications of undue embankment stresses or sloughage. The slopes were stable and dry and no seepage near the toe of the embankment was detected.

2. Appurtenant Structures

The visual inspection did not detect any structural instabilities of the control tower or outlet works. A small amount of cracking of the spillway abutment walls had occurred, but they were not a result of structural instability. The erosion which was reported in the approach channel and at the end of the stilling basin wall indicates that heavier riprap is required.

B. Design and Construction Data

1. Embankment

The available engineering data listed in Section 2.1.B indicates that the dam was designed in accordance with acceptable engineering practice. The embankment section is adequate for this type of dam. The presence of an inspector and the regular visits and reports of the designer during the construction period insure that the fill was placed with good workmanship.

2. Appurtenant Structures

Although no design criteria or analysis was available for the appurtenant structures, the construction drawings show detailed plans of the conduit and the control tower. The conduit has three concrete cutoff collars, of which one is located in the impervious zone.

The spillway weir is anchored into the shale and the abutments have seepage fins projecting 5.5 feet into the embankment. The spillway chute slab and sloping walls are 10-inches thick, well reinforced and supported on a 8-inch gravel bed with weep drains placed at regular intervals. The structure appears to be adequate for the expected flow conditions.

C. Operating Records

There are no formal records of operation. It is estimated that during Agnes the maximum pool level attained was about 6 feet above the spillway crest. During that storm in 1972, eddies near the forebay entrance dislodged a considerable amount of riprap. This indicates that the training walls are not functioning properly and that the flow lines are not smooth. Riprap was also displaced at the end of the right sloping wall of the stilling basin and the slab was slightly undermined.

D. Post Construction Changes

No changes to the original construction are evident or reported.

E. Seismic Stability

This dam is located in Seismic Zone 1 and it is considered that the static stability is sufficient to withstand minor earthquake induced dynamic forces. No studies or calculations have been made to confirm this assumption.

SECTION 7 - ASSESSMENT AND RECOMMENDATIONS

7.1 DAM ASSESSMENT

A. Safety

The visual inspection, the review of available design data and the operational history indicates that Speedwell Forge Dam is in good condition and has been designed in accordance with acceptable engineering practice.

The results of the hydrologic and hydraulic investigations, in accordance with the Corps of Engineers' evaluation guidelines, indicates the spillway discharge and reservoir storage have the capacity for passing 47% of the PMF without overtopping the dam. The calculations in Section 5 show, however, that the depth of the overtopping caused by one-half PMF is less than that judged to cause failure. On the basis of this information, the spillway for this facility is considered to be inadequate but not seriously inadequate.

The results of the inspection survey show an uneven profile of the embankment crest. Refer to Plate A-II in Appendix A. While this condition does not affect the stability of the embankment, providing a uniform elevation at the design crest level would provide some improvement to the capacity of the facility.

B. Adequacy of Information

The information available for review is considered to be adequate to make a reasonable assessment of these facilities.

C. Urgency

It is considered important that the recommendations in this section should be implemented without delay.

D. Necessity for Additional Studies

Additional studies are not required at this time. However, attention should be given to the recommendations presented below.

7.2 RECOMMENDATIONS

A. Facilities

In order to assure a continued satisfactory operation of this dam the following recommendations are made for implementation by the owner:

1. The low areas of the dam breast adjacent to the spillway should be filled and the embankment breast should be raised to its intended design height over the full length.
2. Heavy riprap should be placed at the end of the stilling basin slab.

B. Operation and Maintenance Procedures

It is recommended that the owner develop a formal downstream warning system with its surveillance program to be used during periods of high or prolonged precipitation.

APPENDIX A

CHECKLIST OF VISUAL INSPECTION REPORT

APPENDIX A

CHECK LIST

PHASE I - VISUAL INSPECTION REPORT

| | | | |
|---|--|--|--|
| PA DER # <u>36-257</u> | | NDI NO. PA-00 <u>345</u> | |
| NAME OF DAM <u>Speedwell Forge</u> | | HAZARD CATEGORY <u>High</u> | |
| TYPE OF DAM <u>Earthfill</u> | | | |
| LOCATION <u>Elizabeth</u> | | TOWNSHIP <u>Lancaster</u> COUNTY, PENNSYLVANIA | |
| INSPECTION DATE <u>10/30/78</u> | | WEATHER <u>Sunny</u> TEMPERATURE <u>50's</u> | |
| INSPECTORS: <u>H. Jongsma (Recorder)</u> | | OWNER'S REPRESENTATIVE(s): | |
| <u>A. Bartlett</u> | | <u>Jon Grindall</u> | |
| <u>R. Shireman</u> | | <u>Ray Stichler</u> | |
| <u></u> | | <u></u> | |
| <u></u> | | <u></u> | |
| NORMAL POOL ELEVATION: <u>395</u> | | AT TIME OF INSPECTION: | |
| BREAST ELEVATION: <u>405</u> | | POOL ELEVATION: <u>390.6</u> | |
| SPILLWAY ELEVATION: <u>395</u> | | TAILWATER ELEVATION: <u></u> | |
| MAXIMUM RECORDED POOL ELEVATION: <u>Unknown, estimated at 401</u> | | | |
| GENERAL COMMENTS: | | | |
| <u>As-built drawings in Bellefonte Office of Fish Commission.</u> | | | |

VISUAL INSPECTION
EMBANKMENT

| | OBSERVATIONS AND REMARKS |
|--|--|
| A. SURFACE CRACKS | None. |
| B. UNUSUAL MOVEMENT BEYOND TOE | None. |
| C. SLOUGHING OR EROSION OF EMBANKMENT OR ABUTMENT SLOPES | None noticed on downstream slope, which has a heavy crown vetch cover. None on upstream slope. |
| D. ALIGNMENT OF CREST: HORIZONTAL: VERTICAL: | Good. Good. |
| E. RIPRAP FAILURES | None. |
| F. JUNCTION EMBANKMENT & ABUTMENT OR SPILLWAY | Good. |
| G. SEEPAGE | None detected. Pool about 4 feet below spillway crest. |
| H. DRAINS | None detected. |
| J. GAGES & RECORDER | None. |
| K. COVER (GROWTH) | Upstream: Riprap and crown vetch. Breast: Unmowed grass. Downstream: Crown vetch and weeds. A few bare spots caused by trucks during maintenance work. |

VISUAL INSPECTION
OUTLET WORKS


| | OBSERVATIONS AND REMARKS |
|------------------------|--|
| A. INTAKE STRUCTURE | Concrete tower with stoplogs. |
| B. OUTLET STRUCTURE | 4 feet by 4 feet conduit with wingwalls. |
| C. OUTLET CHANNEL | Riprap - good condition. |
| D. GATES | One 30" x 30" gate for drawdown. Opened during inspection. Stoplogs for normal pool level control. |
| E. EMERGENCY GATE | 30" x 30" gate. |
| F. OPERATION & CONTROL | Opened about six times a year for fish management. |
| G. BRIDGE (ACCESS) | None. |


VISUAL INSPECTION
SPILLWAY

| | OBSERVATIONS AND REMARKS |
|---|---|
| A. APPROACH CHANNEL | Open and clear. Some riprap on banks. Training walls relatively short, causing eddies and erosion of forebay area during Agnes (1972). |
| B. WEIR: Crest Condition Cracks Deterioration Foundation Abutments | Excellent. None. None. Not visible. Good condition - some minor cracks. |
| C. DISCHARGE CHANNEL: Lining Cracks Stilling Basin | Concrete lined with sloping sidewalls & weepholes. No cracks. Concrete endsill with a low flow notch. Riprapped downstream channel. |
| D. BRIDGE & PIERS | None. |
| E. GATES & OPERATION EQUIPMENT | None. |
| F. CONTROL & HISTORY | No records available. Right stilling basin wall undermined during Agnes (1972). Concrete pumped under slab and riprap placed at end of slab. |

VISUAL INSPECTION

| | OBSERVATIONS AND REMARKS |
|---------------------------|--|
| <u>INSTRUMENTATION</u> | |
| Monumentation | None. |
| Observation Wells | None. |
| Weirs | None. |
| Piezometers | None. |
| Staff Gauge | None. |
| Other | |
| <u>RESERVOIR</u> | |
| Slopes | Flat slopes, wooded and agriculture. |
| Sedimentation | None reported. |
| Watershed Description | Upper reaches wooded hills, lower reaches about 50% agriculture. |
| <u>DOWNSTREAM CHANNEL</u> | |
| Condition | Good - natural stream. |
| Slopes | Wooded and some meadows. |
| Approximate Population | 20 |
| No. Homes | About 5 homes before highway crossing. |





PLAN
SPEEDWELL FORGE DAM

SPEEDWELL FORGE DAM
PA. 345
INSPECTION SURVEY

PLATE A-II

Surveyed 10/30/78

APPENDIX B
CHECKLIST OF ENGINEERING DATA

APPENDIX B

CHECK LIST
ENGINEERING DATA

PA DER # 36-257

NDI NO. PA-00 345

NAME OF DAM Speedwell Forge

| ITEM | REMARKS |
|---|---|
| AS-BUILT DRAWINGS | Construction drawings in PennDER files. As-built drawings perhaps in Fish Commission Engineering Office, Bellefonte, Pa. |
| REGIONAL VICINITY MAP | U.S.G.S. Quadrangle, Lititz, Pa. See Plate II, Appendix F |
| CONSTRUCTION HISTORY | Designed by Jordan, McNee, Parnum & Yule, Philadelphia - Contractor, Roger E. Gerhart, Lititz, PA. Completed in January 1966. |
| GENERAL PLAN OF DAM | Plate III, Appendix F. |
| TYPICAL SECTIONS OF DAM | Plates IV, Appendix F and PennDER Files. |
| OUTLETS: PLAN DETAILS CONSTRAINTS DISCHARGE RATINGS | Plates V & VI, Appendix F None None |

ENGINEERING DATA

| ITEM | REMARKS |
|---|---|
| RAINFALL & RESERVOIR RECORDS | None. |
| DESIGN REPORTS | Foundation Report by Design Engineer dated May, 1964. |
| GEOLOGY REPORTS | Included in Foundation Report. |
| DESIGN COMPUTATIONS: HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES | None, except design of spillway based on C-curve. Included in Foundation Report. None. |
| MATERIALS INVESTIGATIONS: BORING RECORDS LABORATORY FIELD | In PennDER files. |
| POST CONSTRUCTION SURVEYS OF DAM | None. |
| BORROW SOURCES | Shown on topographic map in PennDER files. Construction reports indicate that excavation of spillway and forebay area was used in embankment. |
| | |

ENGINEERING DATA

| ITEM | REMARKS |
|--|--|
| MONITORING SYSTEMS | None. |
| MODIFICATIONS | None. |
| HIGH POOL RECORDS | Estimated by approximate waterline on parking lot to be about 6.0 feet during Agnes. |
| POST CONSTRUCTION ENGINEERING STUDIES & REPORTS | None. |
| PRIOR ACCIDENTS OR FAILURE OF DAM Description: Reports: | None. |
| MAINTENANCE & OPERATION RECORDS | No records. Some damage to riprap in forebay area and at end of spillway. |
| SPILLWAY PLAN, SECTIONS AND DETAILS | Plate VII, Appendix F, and files of PennDER. |

ENGINEERING DATA

| ITEM | REMARKS |
|---|--|
| OPERATING EQUIPMENT, PLANS & DETAILS | Plate VI, Appendix F. |
| CONSTRUCTION RECORDS | Some progress reports in PennDER files. |
| PREVIOUS INSPECTION REPORTS & DEFICIENCIES | None. |
| MISCELLANEOUS | In PennDER file is a "Report on the Application" for construction of a dam. |

CHECK LIST
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 50% wooded, 50% agriculture.

ELEVATION:

TOP NORMAL POOL & STORAGE CAPACITY: Elev. 395 970 Acre-FeetTOP FLOOD CONTROL POOL & STORAGE CAPACITY: Elev. 405 2372 Acre-FeetMAXIMUM DESIGN POOL: Elev. 405TOP DAM: Elev. 405

SPILLWAY:

a. Elevation 395b. Type Trapezoidal weir.c. Width 120 feet.d. Length 120 feet and a 60 feet stilling basin.e. Location Spillover Right abutment.f. Number and Type of Gates None.

OUTLET WORKS:

a. Type 4' x 4' cast-in-place reinforced concrete conduit.b. Location Near old streambed.c. Entrance inverts 369.7d. Exit inverts 369.0e. Emergency drawdown facilities 30 x 30-inch sluice gate

HYDROMETEOROLOGICAL GAGES:

a. Type None.b. Location None.c. Records None.MAXIMUM NON-DAMAGING DISCHARGE: 15,000 cfs.

APPENDIX C

HYDROLOGY AND HYDRAULIC CALCULATIONS

APPENDIX C

SUMMARY DESCRIPTION
OF
FLOOD HYDROGRAPH PACKAGE (HEC-1)
DAM SAFETY VERSION

The hydrologic and hydraulic evaluation for this inspection report has employed computer techniques using the Corps of Engineers computer program identified as the Flood Hydrograph Package (HEC-1) Dam Safety Version.

The program has been designed to enable the user to perform two basic types of hydrologic analyses: (1) the evaluation of the overtopping potential of the dam, and (2) the capability to estimate the downstream hydrologic-hydraulic consequences resulting from assumed structural failures of the dam. A brief summary of the computation procedures typically used in the dam overtopping analysis is shown below.

- Development of an inflow hydrograph to the reservoir.
- Routing of the inflow hydrograph(s) through the reservoir to determine if the event(s) analyzed would overtop the dam.
- Routing of the outflow hydrograph(s) of the reservoir to desired downstream locations. The results provide the peak discharge, time of the peak discharge and maximum stage of each routed hydrograph at the outlet of the reach.

The output data provided by this program permits the comparison of downstream conditions just prior to a breach failure with that after a breach failure and the determination as to whether or not there is a significant increase in the hazard to loss of life as a result of such a failure.

The results of the studies conducted for this report are presented in Section 5.

For detailed information regarding this program refer to the Users Manual for the Flood Hydrograph Package (HEC-1) Dam Safety Version prepared by the Hydrologic Engineering Center, U. S. Army Corps of Engineers, Davis, California.

BY RLS DATE 12/7/78
CHKD. BY _____ DATE _____
SUBJECT _____

BERGER ASSOCIATES

SHEET NO. 1 OF _____
PROJECT 08490

SPEEDWELL FORGE DAM

MAXIMUM KNOWN FLOOD AT DAMSITE


THE MAXIMUM KNOWN FLOOD AT SPEEDWELL FORGE DAM OCCURRED IN 1972. AT THAT TIME THE WATER LEVEL IN THE POOL REACHED AN ELEVATION ABOUT 6' HIGHER THAN THE SPILLWAY CREST.

$$\begin{aligned} C &= 3.6 \\ L &= 120' \\ H &= 6' \end{aligned}$$

$$Q = CLH^{3/2}$$

$$= 3.6 \times 120 \times (6)^{1.5}$$

$$= 6349 \text{ CFS} \quad \text{SAY } 6350 \text{ CFS}$$



$C = 3.6$
(REF: M. KANOWITZ)


SPILLWAY CAPACITY

$$\begin{aligned} C &= 3.6 \\ L &= 120' \\ H &= 10' \end{aligned}$$

$$Q = CLH^{3/2}$$

$$= 3.6 \times 120 \times (10)^{1.5}$$

$$= 13661 \text{ CFS} \quad \text{SAY } 13660 \text{ CFS}$$




BY RLS DATE 2/12/79
CHKD. BY _____ DATE _____
SUBJECT _____

BERGER ASSOCIATES

SHEET NO. 2 OF _____
PROJECT D8490

SPEEDWELL FORGE DAM

SPILLWAY RATING CURVE



BY RLS
CHKD. BY
SUBJECT

DATE 12/13/78
DATE

BERGER ASSOCIATES

SHEET NO. 3 OF
PROJECT D 8490

SPEEDWELL FORGE DAM

DISCHARGE THROUGH OUTLET WORKS

ASSUME TAILWATER ELEV = 373

FOR DISCHARGE OF 50 CFS

$$L = 99$$

$$N = .015$$

$$C = 0.6$$

$$A = 16$$

$$R = 1$$

$$Q = \frac{1.486}{N} A R^{2/3} S^{1/2}$$

$$50 = \frac{1.486}{.015} \times 16 \times 1 \times S^{1/2}$$

$$S = .000995 = \frac{H_1}{L}$$

$$H_1 = .0985'$$

$$Q = C A \sqrt{2g H_2}$$

$$A = 2.5^2$$

$$50 = .6 \times 2.5^2 \times (2 \times 32.2 \times H_2)^{1/2}$$

$$H_2 = 2.7605'$$

$$L = 65'$$

$$Q = \frac{1.486}{N} A R^{2/3} S^{1/2}$$

$$50 = \frac{1.486}{.015} \times 16 \times 1 \times S^{1/2}$$

$$S = .000995 = \frac{H_3}{L}$$

$$H_3 = .0647$$

$$H_1 + H_2 + H_3 + 373 = H$$

$$373 + .0985 + 2.7605 + .0647 = 375.9237' \text{ SAY } 376'$$

BY RLS
CHKD. BY
SUBJECT

DATE 12/18/78
DATE

BERGER ASSOCIATES

SHEET NO. 4 OF
PROJECT 08490

SPEEDWELL FORGE DAM

DISCHARGE THROUGH OUTLET WORKS

FOR DISCHARGE OF 135 CFS

$$L = 99'$$

$$Q = \frac{1.486}{N} A R^{2/3} S^{1/2}$$

$$135 = \frac{1.486}{.015} \times 16 \times 1 \times S^{1/2}$$

$$S = .00725 = \frac{H_1}{L}$$

$$H_1 = .718'$$

$$Q = C A \sqrt{2gH_2}$$

$$135 = .6 \times 2.5^2 \times (2 \times 32.2 \times H_2)^{1/2}$$
$$H_2 = 20.124'$$

$$L = 65'$$

$$Q = \frac{1.486}{N} A R^{2/3} S^{1/2}$$

$$135 = \frac{1.486}{.015} \times 16 \times 1 \times S^{1/2}$$

$$S = .00725 = \frac{H_3}{L}$$

$$H_3 = .472$$

$$373 + H_1 + H_2 + H_3 = H$$

$$373 + .718 + 20.124 + .472 = 394.31 \text{ SAY } 394.4'$$

WITH STOP LOGS IN PLACE

BY RLS DATE 1/11/79
CHKD. BY _____ DATE _____
SUBJECT _____

BERGER ASSOCIATES

SHEET NO. 5 OF _____
PROJECT D 8490

SPEEDWELL FORGE

EMBANKMENT RATING

404.7

$$2.7 \times 88 \times .05^{3/2} = 3$$

404.9

$$2.7 \times 88 \times .25^{3/2} = 30$$

$$2.7 \times 370 \times .1^{3/2} = 32$$

$$2.7 \times 58 \times .05^{3/2} = 2$$

$$\Sigma = 64$$

405

$$2.7 \times 88 \times .35^{3/2} = 49$$

$$2.7 \times 370 \times .2^{3/2} = 89$$

$$2.7 \times 190 \times .05^{3/2} = 6$$

$$2.7 \times 58 \times .15^{3/2} = 9$$

$$\Sigma = 153$$

405.2

$$2.7 \times 89 \times .55^{3/2} = 97$$

$$2.7 \times 370 \times .4^{3/2} = 253$$

$$2.7 \times 190 \times .25^{3/2} = 64$$

$$2.7 \times 367 \times .2^{3/2} = 89$$

$$2.7 \times 58 \times .35^{3/2} = 32$$

$$\Sigma = 535$$

405.5

$$2.7 \times 88 \times .85^{3/2} = 186$$

$$2.7 \times 370 \times .7^{3/2} = 585$$

$$2.7 \times 190 \times .55^{3/2} = 209$$

$$2.7 \times 367 \times .5^{3/2} = 350$$

$$2.7 \times 58 \times .65^{3/2} = 82$$

$$\Sigma = 1412$$

406

$$2.7 \times 88 \times 1.35^{3/2} = 373$$

$$2.7 \times 370 \times 1.2^{3/2} = 1313$$

$$2.7 \times 190 \times 1.05^{3/2} = 552$$

$$2.7 \times 367 \times 1^{3/2} = 991$$

$$2.7 \times 58 \times 1.15^{3/2} = 193$$

$$\Sigma = 3422$$

407

$$2.7 \times 88 \times 2.35^{3/2} = 856$$

$$2.7 \times 370 \times 2.2^{3/2} = 3260$$

$$2.7 \times 190 \times 2.05^{3/2} = 1506$$

$$2.7 \times 367 \times 2^{3/2} = 2803$$

$$2.7 \times 58 \times 2.15^{3/2} = 494$$

$$\Sigma = 8919$$

BY RLS DATE 2/12/79
CHKD. BY _____ DATE _____
SUBJECT _____


BERGER ASSOCIATES

SHEET NO. 6 OF _____
PROJECT DB 490

SPEEDWELL FORGE DAM

DISCHARGE CAPACITY CURVE

INCLUDES SPILLWAY AND EMBANKMENT



BY RLS DATE 12/28/78
CHKD. BY _____ DATE _____
SUBJECT _____

BERGER ASSOCIATES

SHEET NO. 7 OF _____
PROJECT D8490

SPEEDWELL FORGE DAM

SIZE CLASSIFICATION

MAXIMUM STORAGE = 2299 ACRE-Feet

MAXIMUM HEIGHT = 35 FEET

SIZE CLASSIFICATION IS INTERMEDIATE.

HAZARD CLASSIFICATION

SEVERAL HOUSES AND FARM BUILDINGS SIT
ALONG THE STREAM CHANNEL ABOUT 1000
FEET DOWNSTREAM OF THE DAM.

USE "HIGH".

RECOMMENDED SPILLWAY DESIGN FLOOD

THE ABOVE CLASSIFICATIONS INDICATE USE
OF AN SDF EQUAL TO THE PROBABLE
MAXIMUM FLOOD.

BY RLS DATE 1/3/79
CHKD. BY DATE
SUBJECT

BERGER ASSOCIATES

SHEET NO. 8 OF
PROJECT D8490

SPEEDWELL FORGE DAM

HEC-1 DATA

DRAINAGE AREA = 24.1 SQ. MI.

SUSQUEHANNA BASIN REGION 15C

CP = 0.82

CT = 2.78

LONGEST WATER COURSE = 57600' = 10.91 MI.

L TO CENTROID = 31000' = 5.87 MI.

$$TP = CT (L \times LCA)^3$$

$$TP = 9.68$$

RAINFALL (HMR-33)

INDEX = 23.3"

ZONE 6

INCREMENTAL RAINFALL

6 HR = 104 %

12 HR = 114 %

24 HR = 123 %

48 HR = 135 %

PLANIMETERED AREAS (FROM CONSTRUCTION DRAWINGS)

ELEV.: 380 = 17.97 ACRES

385 40.12

390 73.71

395 106.4

400 135.33

405 185.83

420 357.82 (FROM QUAD SHEET)

ZERO STORAGE ELEV = 380 - (STORAGE \times 3 / AREA)

ELEV = 363.3


BY RLS DATE 2/13/79
CHKD. BY _____ DATE _____
SUBJECT _____

BERGER ASSOCIATES

SHEET NO. 9 OF _____
PROJECT D8490

SPEEDWELL FORGE DAM

SPILLWAY CAPACITY CURVE




BY RLS DATE 2/13/79
CHKD. BY _____ DATE _____
SUBJECT _____

BERGER ASSOCIATES

SHEET NO. 10 OF
PROJECT D 8490

SPEEDWELL FORGE DAM

SPILLWAY CAPACITY CURVE
IMPROVED EMBANKMENT



FLOOD HYDROGRAPH PACKAGE (HEC-1)

DAM SAFETY VERSION JULY 1978

LAST MODIFICATION 21 AUG 78

OVERTOPPING ANALYSIS

1/4

| | | | | | | | | | | | |
|----|----|---------------------------------------|-------|-------|-------|--------|--------|--------|--------|-------|-------|
| 1 | A1 | SPEEDWELL FORGE DAM **** HAMMER CREEK | | | | | | | | | |
| 2 | A2 | ELIZABETH TWP., LANCASTER CO., PA. | | | | | | | | | |
| 3 | A3 | NDI # PA-00345 PA DER # 36-257 | | | | | | | | | |
| 4 | B | 300 | 0 | 15 | 0 | 0 | 0 | 0 | 0 | -4 | 0 |
| 5 | B1 | 5 | | | | | | | | | |
| 6 | J | 1 | 9 | 1 | | | | | | | |
| 7 | J1 | 1 | .9 | .8 | .7 | .6 | .5 | .4 | .3 | .15 | |
| 8 | K | 1 | | | | | | | | | |
| 9 | K1 | INFLOW HYDROGRAPH | | | | | | | | | |
| 10 | M | 1 | 1 | 24.1 | | | | | | 1 | |
| 11 | P | | 23.3 | 104 | 114 | 123 | 135 | | | | |
| 12 | T | | | | | | | 1 | .05 | | |
| 13 | W | 9.68 | .82 | | | | | | | | |
| 14 | X | -1.5 | -.05 | 2 | | | | | | | |
| 15 | K | 1 | 2 | | | | | 1 | | | |
| 16 | K1 | RESERVOIR ROUTING | | | | | | | | | |
| 17 | Y | | | 1 | 0 | | | | | | |
| 18 | Y1 | 1 | | | | | | 970 | -1 | | |
| 19 | Y4 | 395 | 395.5 | 396 | 397 | 398 | 399 | 400 | 401 | 402 | 403 |
| 20 | Y4 | 404 | 404.6 | 404.7 | 404.9 | 405 | 405.2 | 405.5 | 406 | 407 | 408 |
| 21 | Y5 | 0 | 153 | 432 | 1222 | 2245 | 3456 | 4830 | 6350 | 8000 | 9775 |
| 22 | Y5 | 11664 | 12850 | 13054 | 13521 | 13814 | 14608 | 16110 | 19183 | 26877 | 36182 |
| 23 | SA | 0 | 17.97 | 40.12 | 73.71 | 106.40 | 135.33 | 185.83 | 357.82 | | |
| 24 | SE | 363.3 | 380 | 385 | 390 | 395 | 400 | 405 | 420 | | |
| 25 | SS | 395 | | | | | | | | | |
| 26 | SD | 404.6 | | | | | | | | | |
| 27 | K | 99 | | | | | | | | | |

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

| | |
|----------------------|---|
| RUNOFF HYDROGRAPH AT | 1 |
| ROUTE HYDROGRAPH TO | 2 |
| END OF NETWORK | |

FLOOD HYDROGRAPH PACKAGE (HEC-1)

DAM SAFETY VERSION JULY 1978

LAST MODIFICATION 21 AUG 78

RUN DATE# 79/02/13.
TIME# 06.00.07.

SPEEDWELL FORGE DAM **** HAMMER CREEK
ELIZABETH TWP., LANCASTER CO., PA.
NDI # PA-00345 PA DER # 36-257

JOB SPECIFICATION

| NQ | NHR | NMIN | IDAY | IHR | IMIN | METRC | IPLT | IPRT | NSTAN |
|-----|-----|------|-------|-----|-------|-------|------|------|-------|
| 300 | 0 | 15 | 0 | 0 | 0 | 0 | 0 | -4 | 0 |
| | | | JOPER | NWT | LROPT | TRACE | | | |
| | | | 5 | 0 | 0 | 0 | | | |

MULTI-PLAN ANALYSES TO BE PERFORMED

NPLAN=1 NRTIO=9 LRTIO=1

RTTNC= 1.00 00 00 70 10 00 10 10 10

300 0 15 0 0 0 0 0 0 -4 0
 JOPER NWT LROPT TRACE
 5 0 0 0

2/4

MULTI-PLAN ANALYSES TO BE PERFORMED

NPLAN= 1 NRTIO= 9 LRTIO= 1
 RTIOS= 1.00 .90 .80 .70 .60 .50 .40 .30 .15

SUB-AREA RUNOFF COMPUTATION

INFLOW HYDROGRAPH

ISTAO ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUTO
 1 0 0 0 0 0 1 0 0

HYDROGRAPH DATA

IHYDG IUNG TAREA SNAP TRSDA TRSPC RATIO ISNOW ISAME LOCAL
 1 1 24.10 0.00 24.10 0.00 0.000 0 1 0

PRECIP DATA

SPFE PMS R6 R12 R24 R48 R72 R96
 0.00 23.30 104.00 114.00 123.00 135.00 0.00 0.00

TRSPC COMPUTED BY THE PROGRAM IS .829

LOSS DATA

LROPT STRKR DLTR RTIOL ERAIN STRKS RTIOK STRTL CNSTL ALSMX RTIMP
 0 0.00 0.00 1.00 0.00 0.00 1.00 1.00 .05 0.00 0.00

UNIT HYDROGRAPH DATA

TP= 9.68 CP= .82 NTA= 0

RECESSION DATA

STRTO= -1.50 DRCSN= -.05 RTIOR= 2.00

UNIT HYDROGRAPH100 END-OF-PERIOD ORDINATES, LAG= 9.60 HOURS, CP= .81 VOL= .99

| | | | | | | | | | |
|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| 8. | 29. | 60. | 96. | 136. | 179. | 224. | 270. | 318. | 367. |
| 416. | 466. | 516. | 565. | 615. | 665. | 714. | 763. | 811. | 859. |
| 906. | 953. | 999. | 1045. | 1090. | 1134. | 1177. | 1215. | 1249. | 1278. |
| 1302. | 1323. | 1339. | 1352. | 1361. | 1367. | 1370. | 1369. | 1365. | 1359. |
| 1350. | 1337. | 1322. | 1305. | 1284. | 1260. | 1234. | 1204. | 1170. | 1132. |
| 1089. | 1038. | 976. | 912. | 852. | 796. | 743. | 694. | 649. | 606. |
| 566. | 529. | 494. | 461. | 431. | 403. | 376. | 351. | 328. | 307. |
| 287. | 268. | 250. | 234. | 218. | 204. | 190. | 178. | 166. | 155. |
| 145. | 135. | 127. | 118. | 110. | 103. | 96. | 90. | 84. | 79. |
| 73. | 69. | 64. | 60. | 56. | 52. | 49. | 46. | 43. | 40. |

0

END-OF-PERIOD FLOW

MO.DA HR.MN PERIOD RAIN EXCS LOSS COMP 0 MO.DA HR.MN PERIOD RAIN EXCS LOSS COMP 0

SUM 26.07 23.62 2.45 1464632.
 (662.)(600.)(62.)(41473.76)

HYDROGRAPH ROUTING

HYDROGRAPH ROUTING

3/4

RESERVOIR ROUTING

| ISTAD | ICOMP | IECON | ITAPE | JPLT | JPRT | INAME | ISTAGE | IAUTO |
|-------|-------|-------|-------|------|------|-------|--------|-------|
| 2 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 |

ROUTING DATA

| QLOSS | CLOSS | AVG | IRES | ISAME | IOPT | IPMP | LSTR |
|-------|-------|------|------|-------|------|------|------|
| 0.0 | 0.000 | 0.00 | 1 | 0 | 0 | 0 | 0 |

| NSTPS | NSTD | LAG | AMSK | X | TSK | STORA | ISPRAT |
|-------|------|-----|-------|-------|-------|-------|--------|
| 1 | 0 | 0 | 0.000 | 0.000 | 0.000 | 970. | -1 |

| STAGE | 395.0 | 395.5 | 396.0 | 397.0 | 398.0 | 399.0 | 400.0 | 401.0 | 402.0 | 403.0 |
|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| | 404.0 | 404.6 | 404.7 | 404.9 | 405.0 | 405.2 | 405.5 | 406.0 | 407.0 | 408.0 |

| FLOW | 0. | 153. | 432. | 1222. | 2245. | 3456. | 4830. | 6350. | 8000. | 9775. |
|------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|
| | 11664. | 12850. | 13054. | 13521. | 13814. | 14608. | 16110. | 19183. | 26877. | 36182. |

| SURFACE AREA= | 0. | 18. | 40. | 74. | 106. | 135. | 186. | 358. |
|---------------|----|-----|-----|-----|------|------|------|------|
|---------------|----|-----|-----|-----|------|------|------|------|

| CAPACITY= | 0. | 100. | 242. | 522. | 970. | 1573. | 2372. | 6380. |
|-----------|----|------|------|------|------|-------|-------|-------|
|-----------|----|------|------|------|------|-------|-------|-------|

| ELEVATION= | 363. | 380. | 385. | 390. | 395. | 400. | 405. | 420. |
|------------|------|------|------|------|------|------|------|------|
|------------|------|------|------|------|------|------|------|------|

| CREL | SPWID | COGW | EXPW | ELEVL | COQL | CAREA | EXPL |
|-------|-------|------|------|-------|------|-------|------|
| 395.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |

DAM DATA

| TOPEL | COQD | EXPD | DAMWID |
|-------|------|------|--------|
| 404.6 | 0.0 | 0.0 | 0. |

ITERATIVE SOLUTION DID NOT CONVERGE 194 1 0.000 4.070E+02 -5.039E+02 4.070E+02 8.200E+02

PEAK OUTFLOW IS 27833. AT TIME 48.50 HOURS

PEAK OUTFLOW IS 24686. AT TIME 48.75 HOURS

PEAK OUTFLOW IS 21945. AT TIME 48.75 HOURS

PEAK OUTFLOW IS 19183. AT TIME 48.75 HOURS

PEAK OUTFLOW IS 16432. AT TIME 48.75 HOURS

PEAK OUTFLOW IS 13470. AT TIME 49.50 HOURS

PEAK OUTFLOW IS 10760. AT TIME 49.50 HOURS

PEAK OUTFLOW IS 8063. AT TIME 49.50 HOURS

PEAK OUTFLOW IS 4018. AT TIME 49.50 HOURS

1
4/4

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

| OPERATION | STATION | AREA | PLAN | RATIOS APPLIED TO FLOWS | | | | | | | | |
|---------------|---------|--------|------|-------------------------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| | | | | RATIO 1 | RATIO 2 | RATIO 3 | RATIO 4 | RATIO 5 | RATIO 6 | RATIO 7 | RATIO 8 | RATIO 9 |
| | | | | 1.00 | .90 | .80 | .70 | .60 | .50 | .40 | .30 | .15 |
| HYDROGRAPH AT | 1 | 24.10 | 1 | 27477. | 24730. | 21982. | 19234. | 16486. | 13739. | 10991. | 8243. | 4122. |
| | (| 62.42) | (| 778.08) | (700.27) | (622.46) | (544.65) | (466.85) | (389.04) | (311.23) | (233.42) | (116.71) |
| ROUTED TO | 2 | 24.10 | 1 | 27437. | 24690. | 21942. | 19190. | 16420. | 13445. | 10758. | 8066. | 4016. |
| | (| 62.42) | (| 776.92) | (699.13) | (621.32) | (543.41) | (464.96) | (380.73) | (304.65) | (228.41) | (113.72) |

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1

| | INITIAL VALUE | SPILLWAY CREST | TOP OF DAM |
|-----------|---------------|----------------|------------|
| ELEVATION | 395.00 | 395.00 | 405.00 |
| STORAGE | 970. | 970. | 2372. |
| OUTFLOW | 0. | 0. | 13661. |

| RATIO OF PHF | MAXIMUM RESERVOIR W.S.ELEV | MAXIMUM DEPTH OVER DAM | MAXIMUM STORAGE AC-FT | MAXIMUM OUTFLOW CFS | DURATION OVER TOP HOURS | TIME OF MAX OUTFLOW HOURS | TIME OF FAILURE HOURS |
|--------------|----------------------------|------------------------|-----------------------|---------------------|-------------------------|---------------------------|-----------------------|
| 1.00 | 407.15 | 2.15 | 2795. | 27437. | 11.00 | 48.75 | 0.00 |
| .90 | 406.82 | 1.82 | 2727. | 24690. | 10.25 | 48.75 | 0.00 |
| .80 | 406.47 | 1.47 | 2656. | 21942. | 9.00 | 48.75 | 0.00 |
| .70 | 406.08 | 1.08 | 2579. | 19190. | 7.75 | 48.75 | 0.00 |
| .60 | 405.63 | .63 | 2491. | 16420. | 5.50 | 48.75 | 0.00 |
| .50 | 404.89 | 0.00 | 2353. | 13445. | 0.00 | 49.50 | 0.00 |
| .40 | 403.53 | 0.00 | 2110. | 10758. | 0.00 | 49.50 | 0.00 |
| .30 | 402.04 | 0.00 | 1868. | 8066. | 0.00 | 49.50 | 0.00 |
| .15 | 399.42 | 0.00 | 1495. | 4016. | 0.00 | 49.50 | 0.00 |

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 21 AUG 78

EOI ENCOUNTERED.

FLOOD HYDROGRAPH PACKAGE (HEC-1)

DAM SAFETY VERSION JULY 1978

LAST MODIFICATION 21 AUG 78

OVERTOPPING ANALYSIS
IMPROVED EMBANKMENT

1 A1 SPEEDWELL FORGE DAM *** HAMMER CREEK 1/4

2 A2 ELIZABETH TWP., LANCASTER CO., PA.

3 A3 NDI # PA-00345 PA DER # 36-257

4 B 300 0 15 0 0 0 0 0 -4 0

5 B1 5

6 J 1 9 1

7 J1 1 .9 .8 .7 .6 .5 .4 .3 .15

8 K 1

9 K1 INFLOW HYDROGRAPH

10 H 1 1 24.1 1

11 P 23.3 104 114 123 135

12 T 1 .05

13 W 9.68 .82

14 X -1.5 -.05 2

15 K 1 2 1

16 K1 RESERVOIR ROUTING - (DESIGN ELEV. TOP OF DAM)

17 Y 1 0

18 Y1 1 970

19 #A 0 17.97 40.12 73.71 106.40 135.33 185.83 357.82

20 #E 363.3 380 385 390 395 400 405 420

21 ## 395 120 3.6 1.5

22 #D 405 2.7 1.5 1073

23 K 99

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT 1

ROUTE HYDROGRAPH TO 2

END OF NETWORK

FLOOD HYDROGRAPH PACKAGE (HEC-1)

DAM SAFETY VERSION JULY 1978

LAST MODIFICATION 21 AUG 78

RUN DATE# 79/02/13.

TIME# 05.46.06.

SPEEDWELL FORGE DAM *** HAMMER CREEK

ELIZABETH TWP., LANCASTER CO., PA.

NDI # PA-00345 PA DER # 36-257

JOB SPECIFICATION

| NQ | NHR | NMIN | IDAY | IHR | IMIN | METRC | IPLT | IPRT | NSTAN |
|-----|-----|------|-------|-----|-------|-------|------|------|-------|
| 300 | 0 | 15 | 0 | 0 | 0 | 0 | 0 | -4 | 0 |
| | | | JOPER | NWT | LROPT | TRACE | | | |
| | | | 5 | 0 | 0 | 0 | | | |

MULTI-PLAN ANALYSES TO BE PERFORMED

NPLAN= 1 NRTIO= 9 LRTIO= 1

RTIOS= 1.00 .90 .80 .70 .60 .50 .40 .30 .15

SUB-AREA RUNOFF COMPUTATION

INFLOW HYDROGRAPH

ISTAQ ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUTO
1 0 0 0 0 0 1 0 0

HYDROGRAPH DATA

IHYDG IUHG TAREA SNAP TRSDA TRSPC RATIO ISNOW ISAME LOCAL
1 1 24.10 0.00 24.10 0.00 0.000 0 1 0

PRECIP DATA

SPFE PMS R6 R12 R24 R48 R72 R96
0.00 23.30 104.00 114.00 123.00 135.00 0.00 0.00

TRSPC COMPUTED BY THE PROGRAM IS .829

LOSS DATA

LROPT STRKR DLTGR RTIOL ERAIN STRKS RTIOK STRTL CNSTL ALSMX RTIMP
0 0.00 0.00 1.00 0.00 0.00 1.00 1.00 .05 0.00 0.00

UNIT HYDROGRAPH DATA

TP= 9.68 CP= .82 NTA= 0.

RECESSION DATA

STRTO= -1.50 QRCSN= -.05 RTIOR= 2.00

UNIT HYDROGRAPH 100 END-OF-PERIOD ORDINATES, LAG= 9.60 HOURS, CP= .81 VOL= .99

| | | | | | | | | | |
|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| 8. | 29. | 60. | 96. | 136. | 179. | 224. | 270. | 318. | 367. |
| 416. | 466. | 516. | 565. | 615. | 665. | 714. | 763. | 811. | 859. |
| 906. | 953. | 999. | 1045. | 1090. | 1134. | 1177. | 1215. | 1249. | 1278. |
| 1302. | 1323. | 1339. | 1352. | 1361. | 1367. | 1370. | 1369. | 1365. | 1359. |
| 1350. | 1337. | 1322. | 1305. | 1284. | 1260. | 1234. | 1204. | 1170. | 1132. |
| 1089. | 1038. | 976. | 912. | 852. | 796. | 743. | 694. | 649. | 606. |
| 566. | 529. | 494. | 461. | 431. | 403. | 376. | 351. | 328. | 307. |
| 287. | 268. | 250. | 234. | 218. | 204. | 190. | 178. | 166. | 155. |
| 145. | 135. | 127. | 118. | 110. | 103. | 96. | 90. | 84. | 79. |
| 73. | 69. | 64. | 60. | 56. | 52. | 49. | 46. | 43. | 40. |

END-OF-PERIOD FLOW

NO.DA HR.MN PERIOD RAIN EXCS LOSS COMP Q NO.DA HR.MN PERIOD RAIN EXCS LOSS COMP Q

SUM 26.07 23.62 2.45 1464632.
(662.)(600.)(62.)(41473.76)

HYDROGRAPH ROUTING

RESERVOIR ROUTING - (DESIGN ELEV. TOP OF D

ISTAQ ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUTO
2 1 0 0 0 0 1 0 0

ROUTING DATA

QLOSS CLOSS AVG IRES ISAME IOPT IPMP LSTR
0.0 0.000 0.00 1 0 0 0 0

NSTPS NSTDL LAG AMSKK X TSK STORA ISPRAT
1 0 0 0.000 0.000 0.000 970. 0

HYDROGRAPH ROUTING

RESERVOIR ROUTING - (DESIGN ELEV. TOP OF D

| ISTAQ | ICOMP | IECON | ITAPE | JPLT | JPRT | INAME | ISTAGE | IAUTO |
|-------|-------|-------|-------|------|------|-------|--------|-------|
| 2 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 |

ROUTING DATA

| QLOSS | CLOSS | AVG | IRES | ISAME | IOPT | IPMP | LSTR |
|-------|-------|------|------|-------|------|------|------|
| 0.0 | 0.000 | 0.00 | 1 | 0 | 0 | 0 | 0 |

| NSTPS | NSTD | LAG | AMSK | X | TSK | STORA | ISPRAT |
|-------|------|-----|-------|-------|-------|-------|--------|
| 1 | 0 | 0 | 0.000 | 0.000 | 0.000 | 970. | 0 |

| | | | | | | | | |
|---------------|----|-----|-----|-----|------|------|------|------|
| SURFACE AREA= | 0. | 18. | 40. | 74. | 106. | 135. | 186. | 358. |
|---------------|----|-----|-----|-----|------|------|------|------|

| | | | | | | | | |
|-----------|----|------|------|------|------|-------|-------|-------|
| CAPACITY= | 0. | 100. | 242. | 522. | 970. | 1573. | 2372. | 6380. |
|-----------|----|------|------|------|------|-------|-------|-------|

| | | | | | | | | |
|------------|------|------|------|------|------|------|------|------|
| ELEVATION= | 363. | 380. | 385. | 390. | 395. | 400. | 405. | 420. |
|------------|------|------|------|------|------|------|------|------|

| CREL | SPWID | COOW | EXPW | ELEV | COOL | CAREA | EXPL |
|-------|-------|------|------|------|------|-------|------|
| 395.0 | 120.0 | 3.6 | 1.5 | 0.0 | 0.0 | 0.0 | 0.0 |

DAM DATA

| TOPEL | COOD | EXPD | DAMWID |
|-------|------|------|--------|
| 405.0 | 2.7 | 1.5 | 1073. |

PEAK OUTFLOW IS 27437. AT TIME 48.75 HOURS

PEAK OUTFLOW IS 24690. AT TIME 48.75 HOURS

PEAK OUTFLOW IS 21942. AT TIME 48.75 HOURS

PEAK OUTFLOW IS 19190. AT TIME 48.75 HOURS

PEAK OUTFLOW IS 16420. AT TIME 48.75 HOURS

PEAK OUTFLOW IS 13445. AT TIME 49.50 HOURS

PEAK OUTFLOW IS 10758. AT TIME 49.50 HOURS

PEAK OUTFLOW IS 8066. AT TIME 49.50 HOURS

PEAK OUTFLOW IS 4016. AT TIME 49.50 HOURS

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS

FLows IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
AREA IN SQUARE MILES (SQUARE KILOMETERS)

| OPERATION | STATION | AREA | PLAN | RATIOS APPLIED TO FLOWS | | | | | | | | |
|---------------|---------|----------|------|-------------------------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| | | | | RATIO 1 | RATIO 2 | RATIO 3 | RATIO 4 | RATIO 5 | RATIO 6 | RATIO 7 | RATIO 8 | RATIO 9 |
| | | | | 1.00 | .90 | .80 | .70 | .60 | .50 | .40 | .30 | .15 |
| HYDROGRAPH AT | 1 | 24.10 | 1 | 27477. | 24730. | 21982. | 19234. | 16486. | 13739. | 10991. | 8243. | 4122. |
| | | (62.42) | | (778.08) | (700.27) | (622.46) | (544.65) | (466.85) | (389.04) | (311.23) | (233.42) | (116.71) |
| ROUTED TO | 2 | 24.10 | 1 | 27833. | 24686. | 21945. | 19183. | 16432. | 13470. | 10760. | 8063. | 4018. |
| | | (62.42) | | (788.14) | (699.04) | (621.41) | (543.21) | (465.32) | (381.42) | (304.69) | (228.32) | (113.79) |

SUMMARY OF DAM SAFETY ANALYSIS

| PLAN 1 | | INITIAL VALUE | SPILLWAY CREST | TOP OF DAM |
|--------------|-----------|---------------|----------------|------------|
| | ELEVATION | 395.00 | 395.00 | 404.60 |
| | STORAGE | 970. | 970. | 2299. |
| | OUTFLOW | 1. | 0. | 12850. |

| RATIO OF PMF | MAXIMUM RESERVOIR W.S.ELEV | MAXIMUM DEPTH OVER DAM | MAXIMUM STORAGE AC-FT | MAXIMUM OUTFLOW CFS | DURATION OVER TOP HOURS | TIME OF MAX OUTFLOW HOURS | TIME OF FAILURE HOURS |
|--------------------|----------------------------------|------------------------------|-----------------------------|---------------------------|-------------------------------|---------------------------------|-----------------------------|
| 1.00 | 407.02 | 2.42 | 2767. | 27833. | 11.75 | 48.50 | 0.00 |
| .90 | 406.72 | 2.12 | 2705. | 24686. | 10.75 | 48.75 | 0.00 |
| .80 | 406.36 | 1.76 | 2634. | 21945. | 9.75 | 48.75 | 0.00 |
| .70 | 406.00 | 1.40 | 2563. | 19183. | 8.50 | 48.75 | 0.00 |
| .60 | 405.55 | .95 | 2476. | 16432. | 6.50 | 48.75 | 0.00 |
| .50 | 404.88 | .28 | 2350. | 13470. | 3.00 | 49.50 | 0.00 |
| .40 | 403.52 | 0.00 | 2109. | 10760. | 0.00 | 49.50 | 0.00 |
| .30 | 402.04 | 0.00 | 1868. | 8063. | 0.00 | 49.50 | 0.00 |
| .15 | 399.41 | 0.00 | 1494. | 4018. | 0.00 | 49.50 | 0.00 |

FLOOD HYDROGRAPH PACKAGE (HEC-1)

DAM SAFETY VERSION JULY 1978
LAST MODIFICATION 21 AUG 78

EOL ENCOUNTERED.

N>

APPENDIX D
GEOLOGIC REPORT

APPENDIX D

GEOLOGIC REPORT

Bedrock - Dam and Reservoir

Formation: Cocalico Formation.

Lithology: The Cocalico Formation consists of dark gray to bluish black fissile shale, that weathers to a light brown color. Locally the shale is limy and a few beds of shaly limestone are present. Some beds of hard, brown sandstone are also present in the formation. Bedding is frequently obscure and the dominant parting is fracture cleavage.

Structure

The beds at Speedwell Forge have been intensely folded and thrust. Isoclinal, recumbent folds have been mapped in the area. Folding is hard to recognize in the Cocalico because the bedding is frequently obscured by cleavage. Fracture cleavage in the area strikes N70° to 90°E and dips gently to the north or south.

Fracture traces in the area trend: N10°E, N20°E, N30°E, N60°E, N80°E, N15°W and N80°W.

Overburden

Overburden here consists of weathered bedrock, and some alluvium. The weathered zone of the bedrock is nine to twenty feet thick. The alluvium in the creek valley was nine to fourteen feet thick, and consisted of clay, silt, sand and some sand and gravel.

Aquifer Characteristics

The Cocalico shale is an essentially impermeable rock, and ground water movement is along cleavage planes, joints and fractures and to a lesser extent along bedding. The upper weathered zone is quite permeable. Permeability decreased with depth in the fresh rock. Some solution of the more limy beds by ground water movement is possible. Solution openings are generally clogged with clay derived from the decomposed shale.


Discussion

The dam was constructed with a cutoff trench dug into fresh rock. Some movement of water through fractures beneath the cutoff trench is possible. Enlargement of these fractures by solution is theoretically possible in the limy beds, but is inhibited by the large amount of clay present. Large scale leakage is considered unlikely, and small leakage is unlikely to increase.

Sources of Information

1. Meisler, Harold and Becher, A.E. (1971) "Hydrogeology of the Lancaster 15-Minute Quadrangle". Pa. Geological Survey Ground Water Report W26.
2. Air Photographs, dated 1969, scale 1:24,000.
3. Core boring logs in file.


GEOLOGIC MAP - Hammer Creek Dam



(geology from Pa. Geol. Surv. Report W26)

- Oco Cocalico Fm.
- Oa Annville Fm.
- Oo Ontelaunee Fm.


--- air photo fracture trace



CONTOUR INTERVAL 20 FEET
 DOTTED LINES REPRESENT 10-FOOT CONTOURS
 DATUM IS MEAN SEA LEVEL

APPENDIX E
PHOTOGRAPHS

APPENDIX E



Upstream Slope
and Forebay



Upstream Slope
and
Control Structure




Downstream Slope

PA-345
PLATE E-I



Reservoir



Conduit Outlet
Looking Upstream



Conduit Outlet
Channel

PA-345
PLATE E-II



Spillway Weir



Spillway Chute
and
Stilling Basin




Spillway
Downstream Channel


PA-345
PLATE E-III



APPENDIX F


PLATES

APPENDIX F











36-257-12
FILE NUMBER
RECEIVED IN THE OFFICE OF THE WATER & FOREST
RESOURCES BOARD - DEPARTMENT OF FOREST
WATERS ON THE 17 DAY OF Nov 1964
BOSTON, MASS.
FILE NO.







Note: Other Details of Tower on Sheet No. 12



| | | | | | | | | | |
|---|-------------|---|--|--|----------------------|--|--|--|--|
| | | | | | | | | | |
| SUBNO. | CORRECTIONS | | | | | | | | |
| SUBMITTED | | | | | | | | | |
| APPROVED | | ENGINEER | | | | | | | |
| CHECKED BY | | PENNA. FIRM COMMISSION | | | | | | | |
| APPROVED | | <i>[Signature]</i> PENNA. FIRM COMMISSION - ENGINEER | | | | | | | |
| APPROVED | | ASSISTANT DIRECTOR OF ENGINEERING - U.S.A. | | | | | | | |
| CHECKED BY | | THE GENERAL STATE AUTHORITY | | | | | | | |
| ARCH | STRUCT | | | | | | | | |
| THE GENERAL STATE AUTHORITY HARRISBURG PENNSYLVANIA | | | | | | | | | |
| PROJECT NO. G.S.A. - 199-6 | | | | | | | | | |
| CONSTRUCTION OF DAM HAMMER CREEK | | | | | | | | | |
| ELIZABETH TWP. | | | | | LANCASTER CO. PENNA. | | | | |
| JORDAN, MCNEE, PARNUM & VYLE ARCHITECTS & ENGINEERS 1225 VINE ST PHILADELPHIA 7, PENNA. | | | | | | | | | |
| CONTROL TOWER & CONDUIT | | | | | | | | | |

PA. 345
PLATE V






FILE NUMBER



REC'D _____ FOR _____
SEE REPORT NO. _____

Dir. Dams

JUN 12 1965
C. H. McDaniel
State Police


[illegible]

PA. 345
PLATE VI




PROFILE OF SPILLWAY
Scale 1" = 10'

SECT
Scale




SECTION D-D
Scale 1/2" = 1'-0"


36-257-6
FILE NUMBER
DESIGNED IN THE OFFICE OF THE WATER & POWER ENGINEER BOARD, DEPARTMENT OF PUBLIC WORKS, CITY OF PHILADELPHIA
DATE: 7/25/57
BY: [Signature]
RECD: _____ FOR: _____
SEE REPORT NO. _____
Div. Dam




SECTION J-J
Scale 1/2" = 1'-0"




SECTION E-E
Scale 1/2" = 1'-0"




SECTION K-K
Scale 1/2" = 1'-0"



SECTION H-H
Scale 1/2" = 1'-0"



SECTION F-F
Scale 1/2" = 1'-0"



SECTION G-G
Scale 1/2" = 1'-0"

NOTE: All concrete to be G.S.A. Concrete
Design Data
Max Design Fdn Pressure 3 Tons per sq. ft.
Live Load
100 p.s.i., fs = 20,000 p.s.i., ft = 3,000 p.s.i.
Concrete
28 day compressive strength 3,300
p.s.i. (minimum)

| | |
|--|--|
| SYMBOL | CORRECTIONS |
| SUBMITTED | ENGINEER |
| APPROVED | PENNA. FISH COMMISSION |
| APPROVED | Shannon R. Miller, PE PENNA. FISH COMMISSION - ENGINEER |
| APPROVED | ASSISTANT DIRECTOR OF ENGINEERING - G.S.A. |
| CHECKED BY | THE GENERAL STATE AUTHORITY |
| DATE | 7/25/57 |
| THE GENERAL STATE AUTHORITY HARRISBURG, PENNSYLVANIA | |
| PROJECT NO. G.S.A. - 199-6 | |
| CONSTRUCTION OF DAM HAMMER CREEK | |
| ELIZABETH TWP. LANCASTER CO. PENNA. | |
| JORDAN, MC NEE, PARSONS & YULE ARCHITECTS & ENGINEERS 1825 VINE ST. PHILADELPHIA 7, PENNA. | |
| PLAN & PROFILE - SPILLWAY | |
| DESIGNED BY | JOHN D. GAY |
| CHECKED BY | DAVE |
| SCALE | AS SHOWN |

PA. 345
PLATE VII

SECTION B-B
Scale 1/2" = 1'-0"

